

DUBLIN PORT COMPANY

NOTICE TO MARINERS

No. 17 of 2008

Temporary Buoy

Notice is hereby given that :

A yellow buoy has been temporarily placed in position

Lat. 53° 20.54' North Long. 006° 11.73' West

Characteristic: Fl. Y 4 sec

The buoy lies to the north of a semi-submerged obstruction that lies outside of the channel and east of the mooring dolphin for berth 47. This buoy will remain until such time as the obstruction is removed.

This Notice is self-canceling.

Captain David T. Dignam
Harbour Master

12th November 2008